

Annex to declaration of accreditation (scope of accreditation)
Normative document: EN ISO/IEC 17020:2012
Registration number: **I 137, type C**

of **SGS Search Laboratorium B.V.**

This annex is valid from: **03-07-2024** to **01-01-2026**

Replaces annex dated: **01-07-2022**

Location(s) where activities are performed under accreditation

Head Office

Meerstraat 7
5473 AA
Heeswijk Dinther
Nederland

Location	Abbreviation/ location code
Meerstraat 7 5473 AA Heeswijk Dinther Nederland	HD

No.	Field of inspection	Type and range of inspection	Methods & procedures ¹	Location
Sampling				
1	Ambient air	Sampling for the purpose of determining the asbestos fibre concentration using scanning electron microscopy and X-ray microanalysis	NEN 2991 L09	HD
2	Settled dust	Sampling for the purpose of asbestos fibre content using scanning electron microscopy and X-ray microanalysis	NEN 2991 L14	HD
3	Bulk materials	Sampling for the purpose of asbestos fibre content using stereo- and polarized light microscopy	NEN 5896 L08	HD

¹ If no date or version number is mentioned for a normative document, the accreditation concerns the most current version of the document or scheme.

¹ If there is a referral to a code starting with NAW, NAP, EA or IAF, this concerns a scheme mentioned on the [RvA-BR010-lijst](#).

This annex has been approved by the Board of the
Dutch Accreditation Council, on its behalf,

J.A.W.M. de Haas

Annex to declaration of accreditation (scope of accreditation)
 Normative document: EN ISO/IEC 17020:2012
 Registration number: **I 137, type C**

of **SGS Search Laboratorium B.V.**

This annex is valid from: **03-07-2024 to 01-01-2026**

Replaces annex dated: **01-07-2022**

No.	Field of inspection	Type and range of inspection	Methods & procedures ¹	Location
Final inspection after removing asbestos containing materials				
4	Indoor and outdoor location after risk class 1 asbestos removal Outdoor location after risk class 2 and 2A asbestos removal and risk class 2A exceptions asbestos removal	Final inspection after removing asbestos-containing materials	NEN 2990:2020+C1:2020 L10	HD
5	Indoor location after risk class 2 asbestos removal and risk class 2A exceptions asbestos removal	Final inspection after removing asbestos-containing materials	NEN 2990:2020+C1:2020 L10, L11	HD
6	Indoor location after risk class 2A asbestos removal	Final inspection after removing asbestos-containing materials	NEN 2990:2020+C1:2020 L10, L11	HD
7	Indoor and outdoor location No legal clearance required	Check on effectiveness of remediation/cleaning after one of the following activities: – After removal of asbestos from a work area for which no legal final assessment in accordance with NEN2990 is required – After cleaning of a deco unit – After sampling as part of an asbestos inventory without legal obligation to follow-up research After activities on or removal of Man Made Mineral Fibers	Own method as described in procedure L10-A8	HD