

Annex to declaration of accreditation (scope of accreditation)
Normative document: EN ISO/IEC 17020:2012
Registration number: **I 268, type C**

of **Défect Milieu Services B.V.**

This annex is valid from: **21-03-2024** to **01-08-2028**

Replaces annex dated: **01-07-2022**

Location(s) where activities are performed under accreditation

Head Office

Blauw-roodlaan 154
2718 SK
Zoetermeer
Nederland

Location	Abbreviation/ location code
Blauw-roodlaan 154 2718 SK Zoetermeer Nederland	Zoe

No.	Field of inspection	Type and range of inspection	Methods & procedures ¹	Location
Sampling				
1	Ambient air	Sampling for the purpose of determining the asbestos fibre concentration using scanning electron microscopy and X-ray microanalysis	NEN 2991	Zoe
2	Settled dust	Sampling for the purpose of asbestos fibre content using scanning electron microscopy and X-ray microanalysis	NEN 2991	Zoe
3	Bulk materials	Sampling for the purpose of asbestos fibre content using stereo- and polarized light microscopy	NEN 5896	Zoe

¹ If no date or version number is mentioned for a normative document, the accreditation concerns the most current version of the document or scheme.

¹ If there is a referral to a code starting with NAW, NAP, EA or IAF, this concerns a scheme mentioned on the [RvA-BR010-lijst](#).

This annex has been approved by the Board of the
Dutch Accreditation Council, on its behalf,

J.A.W.M. de Haas

Annex to declaration of accreditation (scope of accreditation)
 Normative document: EN ISO/IEC 17020:2012
 Registration number: **I 268, type C**

of **Déetect Milieu Services B.V.**

This annex is valid from: **21-03-2024** to **01-08-2028**

Replaces annex dated: **01-07-2022**

No.	Field of inspection	Type and range of inspection	Methods & procedures ¹	Location
Final inspection after removing asbestos-containing materials				
4	Indoor and outdoor location after risk class 1 asbestos removal Outdoor location after risk class 2 and 2A asbestos removal and risk class 2A exceptions asbestos removal	Final inspection after removing asbestos-containing materials	NEN 2990:2020 +C1:2020	Zoe
5	Indoor location after risk class 2 asbestos removal and risk class 2A exceptions asbestos removal	Final inspection after removing asbestos-containing materials	NEN 2990:2020 +C1:2020	Zoe
6	Indoor location after risk class 2A asbestos removal	Final inspection after removing asbestos-containing materials	NEN 2990:2020 +C1:2020	Zoe